


# SCHEMATIC VIEW OF GOONGUMPAS SUPPLY PIPES (E&OE MARCH 2015)

ANIMAL TROUGHS ON GOON FARM LAND FED FROM A GOON FARM PIPE WITH A SERIOUS "LEAK". THE LEFT TROUGH ALSO SUPPLIED THE CABIN WHICH IN TURN (AS FROM JANUARY 2015) SUPPLIED THE LANYON SHED. THE SUPPLY TO THESE TROUGHS CEASED WHEN WE TURNED THE STOP TAP AT TAILINGS END OFF ON 2 FEBRUARY 2015 SO IT CAN ONLY BE THAT THE WINTER COTTAGE, GHE AND ANNEXE SUPPLY WAS CONNECTED TO THE GOON FARM LEAKY PIPE AND, DESPITE THE LEAK, INCREASED THE PRESSURE SUFFICIENTLY TO GET WATER TO THESE TROUGHS AND BEYOND. (EXCEPT WHEN ANOTHER USER CONNECTED FOR ABOUT AN HOUR DAILY WHICH CAUSED THE PRESSURE TO DROP TO SUCH AN EXTENT THE SUPPLY STOPPED).



KNOWN STOP TAPS ON METERED SUPPLIES

STOP TAP(S) ON A PIPE THAT CONNECTS OUR SUPPLY TO THE GOON FARM PIPE WITH A "LEAK" AND THUS INCREASES THE PRESSURE SUFFICIENTLY TO PROVIDE THE TWO TROUGHS ON GOON FARM LAND WITH WATER AND ALSO THE CABIN AND LANYON SHED WHICH ARE SUPPLIED FROM ONE OF THESE TROUGHS.

ON 2 FEBRUARY 2015 GOON FARM APPARENTLY TURNED OFF THESE STOP TAPS WHICH RESULTED IN OUR SUPPLY NO LONGER REGISTERING A LEAK BUT THE "OTHER USER/S" CONTINUED TO DRAW ABOUT 900 LTRS PER DAY ALTHOUGH, AS THE "LEAK" HAD BEEN "REMOVED" FROM OUR SUPPLY THE WATER DID NOT STOP RUNNING AT OUR PROPERTIES (AS IT HAD FOR ABOUT 7 YEARS) AS THE PRESSURE IN OUR SUPPLY HAD INCREASED CONSIDERABLY WITHOUT THE "LEAK".

HORSE TROUGH BEHIND / TO THE RIGHT OF FIVE ACRES SUSPECTED OF BEING CONNECTED TO SUPPLY TO GHE/WINTER COTTAGE/ANNEXE

TROUGH ON MR LANYON'S LAND CONNECTED TO CARN VIEW SEVERAL YEARS AGO USED BY MR LANYON'S TENANT FOR ABOUT 2 YEARS (NO CHARGE) AND DISCONNECTED (BY CARN VIEW) WHEN OUR SURVEY STARTED IN 2015

STOP TAPS TURNED OFF ON 2 FEBRUARY 2015 (BY GOON FARM) AND CAUSED THE LEAK ON WINTER COTTAGE PIPE TO DISAPPEAR AND THE WATER PRESSURE TO INCREASE TO A LEVEL NOT EXPERIENCED FOR ABOUT 40 YEARS! TURNING OFF THIS TAP ALSO STOPPED THE SUPPLY TO THE TWO ANIMAL TROUGHS ON GOON FARM AND THE SUPPLY TO THE CABIN AND MR LANYON'S TENANT.

HOWEVER IT IS THOUGHT THAT THE LEAK STILL EXISTS (ON GOON FARM LAND) BECAUSE, EVEN WITH THE STOP TAP AT TAILINGS END TURNED OFF, A SMALL AMOUNT OF PRESSURISED WATER GETS THROUGH TO WINTER COTTAGE INDICATING THAT THE STOP TAPS DO NOT COMPLETELY TURN OFF AND ALLOWS WATER TO BACK FLOW FROM THE LEAKY (BUT STILL LIVE) SUPPLY ON GOON FARM.

SUPPLY ON GOON FARM CONNECTED AFTER THEIR ENTRANCE GATE BUT BEFORE THEIR METER (SUSPECTED MAIN LEAK)

STOP TAP AND METER ON GOON FARM TO HARMONY COTTAGE REMOVED WHEN HARMONY COTTAGE INSTALLED NEW PIE TO TAILINGS END