

Peninsula House, Rydon Lane, Exeter EX2 7HR southwestwater.co.uk Freephone 0800 169 11 44 Minicom 0800 169 99 65 Fax 01392 423792

0344 346 2020

Mr J Layte

Goonhill End Cottage Goongumpas Redruth Cornwall TR16 5JL Ref: WaterRegs/RHARRI/30457/1

Telephone: 01392 443322

For the attention of Mr J Layte

Dear Mr Layte

16 April 2015

Non Compliance of the Water Supply (Water Fittings) Regulations 1999 Ref: Goonhill End Cottage, Goongumpas, TR16 5JL

Thank you for the courtesy shown during our recent visit to your premises. During the inspection apparent contraventions of the Water Supply (Water Fittings) Regulations 1999 were found, these are detailed on the attached report.

These contraventions should be corrected within the following time scales.

Fluid Category 5 risks - Within 7 days Fluid Category 4 risks - Within 14 days Fluid Category 3 risks - Within 28 days Other Contraventions - Within 3 months

Please note; double check valves are not appropriate for category 4 or 5 risks.

When the work has been completed please inform Water Regulations Department on 01392 443322 so that a further inspection can be arranged. If you have any difficulty in rectifying any fault within the time scale, please contact me directly in order that interim measures can be discussed.

The Water Supply (Water Fittings) Regulations 1999 have been made under sections 74, 84 and 213 (2) of the Water Industry Act 1991, to prevent waste, misuse, undue consumption, contamination or erroneous measurement of water supplied by a Water Undertaker. Compliance is mandatory.

If you require further information regarding the Water Supply (Water Fittings) Regulations 1999 please contact the Regulations Office at the above address.

Yours sincerely

R.Harrison

Regulations Officer



Page No. 2 of 2

No	1
Location	Roofspace Storage Cistern - Incorrrect float valves fitted (i.e change to pt2 float valves)
Description	1 x Domestic storage cistern - 1/2" Pt1 float operated valve - Not adjustable
Connection	From mains
Fluid Category	. 1
Requirements	Install half inch float operated valve (ball valve) with purpose made mechanical shut off level adjustment.
No	2
Location	General Pipework - no identification of pipework (i.e Rainwater + Mains pipework)
Description	1 x Supply Pipe - Pipework not identifiable in accordance with BS1710
Connection	From mains
Fluid Category	5 and in the story and the Water Strings (West Millians) Regularity and
Requirements	Pipework to be marked or colour coded in accordance with BS1710
No	3
Location	Roofspace Storage System - No Letterbox weir overflow
Description	1 x Domestic storage cistern - No air gap
Connection	From mains
Fluid Category	5 uplaned please inform Wanger
Requirements	Provide type AB air gap or some no less effective device or arrangmeent, or permanantly disconnect from the Company's supply

RECOMMENDATIONS