

Subject: Results of first and second Water survey at Goongumpas

From: John Layte <john@layte.com>

Date: 11/02/2015 17:01

To: Jacqui.Walls@dc-media.co.uk, West Briton <jreines@c-dm.co.uk>, SWW <customerleakage@southwestwater.co.uk>

CC: john@layte.co.uk, Kath Layte <kath@layte.com>

For the attention of Mr Mathews (West Briton)

Dear Mr Mathews

Further to our recent phone conversatio I enclose the results of our latest survey and a schematic diagram of the area's water supply. I must stress that the suspicion that the horse trough behind Five Acres is connected to our supply (and has been for many years) is only that - a suspicion - I think it is for SWW to prove, not us, but SWW have stated that it is "not their responsibility" as they did with the "leak". We suspect the leak still exists even though it no longer registers on our supply.

It is at least 7 years since we first contacted SWW about the problem we had in that our water supply stopped for about an hour almost every day and over a year since they installed a water meter and discovered what they said was a "leak" and subsequently threatened us with litigation if we didn't fix it.

If you want any more information please contact me.

Regards

JH Layte

Attachments:

[latest meter readings.pdf](#)

201 kB

[SCHEMATIC DIAGRAM GOONGUMPAS WATER SUPPLIES.jpg](#)

226 kB

