

8 JUL.



Peninsula House, Rydon Lane, Exeter EX2 7HR southwestwater.co.uk
Freephone 0800 169 11 44 Minicom 0800 169 99 65 Fax 01392 423792

Mr J Layte
Goonhill End Cottage
Goongumpas
Redruth
Cornwall
TR16 5JL

Ref: WaterRegs/RHARRI/30457/4
Telephone : 01392 443322

For the attention of Mr J Layte
Dear Mr Layte

08 July 2015

Non Compliance of the Water Supply (Water Fittings) Regulations 1999
Ref: Goonhill End Cottag, Goongumpas, TR16 5JLe

Thank you for the courtesy shown during our recent visit to your premises. During the inspection apparent contraventions of the Water Supply (Water Fittings) Regulations 1999 were found, these are detailed on the attached report. These contraventions should be corrected within the following time scales.

- Fluid Category 5 risks - Within 7 days
- Fluid Category 4 risks - Within 14 days
- Fluid Category 3 risks - Within 28 days
- Other Contraventions - Within 3 months

Please note; double check valves are not appropriate for category 4 or 5 risks.

When the work has been completed please inform Water Regulations Department on 01392 443322 so that a further inspection can be arranged. If you have any difficulty in rectifying any fault within the time scale, please contact me directly in order that interim measures can be discussed.

The Water Supply (Water Fittings) Regulations 1999 have been made under sections 74, 84 and 213 (2) of the Water Industry Act 1991, to prevent waste, misuse, undue consumption, contamination or erroneous measurement of water supplied by a Water Undertaker. Compliance is mandatory.

If you require further information regarding the Water Supply (Water Fittings) Regulations 1999 please contact the Regulations Office at the above address.

Yours sincerely

R.Harrison
Regulations Officer



INVESTOR IN PEOPLE

**WATER SUPPLY (WATER FITTINGS) REGULATIONS
SURVEY REPORT
OF**

**Goonhill End Cottage
Goongumpas
Redruth
Cornwall
TR16 5JL**

16 April 2015

Richard Harrison

No 2
Location General Pipework - no identification of pipework (i.e Rainwater + Mains pipework)
Description 1 x Supply Pipe - Pipework not identifiable in accordance with BS1710
Connection From mains
Fluid Category 5
Requirements Pipework to be marked or colour coded in accordance with BS1710

No 3
Location Roofspace Storage System - No Letterbox weir overflow
Description 1 x Domestic storage cistern - No air gap
Connection From mains
Fluid Category 5
Requirements Provide type AB air gap or some no less effective device or arrangement, or permanently disconnect from the Company's supply

RECOMMENDATIONS